



Noise

INTRODUCTION

In welding, cutting, and allied operations, noise may result from the process, the power source, or other equipment. Air carbon arc cutting and plasma arc cutting are examples of processes which are frequently noisy. Engine-driven generators may also be quite noisy. Excessive noise is a known health hazard.

DEFINITION

Scientifically, noise is composed of several frequencies and involves random changes in frequency or amplitude. Sound waves are produced when the air is mechanically disturbed. Sound is measured by its frequency (pitch-high or low) and intensity (loudness). Practically, noise is unwanted or unpleasant sound. It can get in the way of the sounds we would rather hear and often need to hear for safety reasons.

EFFECTS OF OVEREXPOSURE TO NOISE

- Loss of hearing that may be either full or partial and either temporary or permanent.
- Hearing loss may be a temporary threshold shift from which the ears may recover if removed from the noise source.
- The time required to develop permanent hearing loss depends on

individual susceptibility, noise level, and exposure duration.

- There is evidence that excessive noise affects other bodily functions and behavior as well.

HOW TO PROTECT AGAINST NOISE

- Reduce the intensity of the source.
- Shield the source where practical.
- Use engineering control methods, such as room acoustics, to control noise.
- If engineering methods fail to reduce noise to acceptable levels, wear approved personal protective devices such as ear muffs or ear plugs appropriate for the situation.
- Follow OSHA regulations which require a Hearing Conservation Program if noise levels reach 85 dB on an 8-hour, Time Weighted Average (TWA) basis.
- If noise level is questionable, have a certified safety specialist or Industrial Hygienist take measurements and make recommendations.

INFORMATION SOURCES

Occupational Safety and Health Administration (OSHA). *Code of Federal Regulations*, Title 29 Labor, Parts 1910.1 to 1910.1450, available from the U.S.

AWS disclaims liability for any injury to persons or to property, or other damages of any nature whatsoever, whether special, indirect, consequential or compensatory, directly or indirectly resulting from the publication, use of, or reliance on this Safety and Health Fact Sheet. AWS also makes no guaranty or warranty as to the accuracy or completeness of any information published herein.

Government Printing Office,
Superintendent of Documents, P.O. Box
371954, Pittsburgh, PA 15250-7954
(telephone: 800-321-6742; web site:
www.osha.gov).

American Conference of Governmental
Industrial Hygienists (ACGIH). *Threshold
Limit Values for Chemical Substances and
Physical Agents and Biological Exposure
Indices*, available from ACGIH, 1330
Kemper Meadow Drive, Cincinnati, OH
45240-1634 (telephone: 513-742-2020;
web site: www.acgih.org).

Mine Safety and Health Administration
(MSHA). *Code of Federal Regulations*,
Title 30 Mineral Resources, Parts 1 to 199,
available from the U.S. Government
Printing Office, Superintendent of
Documents, P.O. Box 371954, Pittsburgh,
PA 15250-7954 (telephone: 202-693-9400;
web site: www.msha.gov).

TLV is a registered trademark of the ACGIH.

AWS disclaims liability for any injury to persons or to property, or other damages of any nature whatsoever, whether special, indirect, consequential or compensatory, directly or indirectly resulting from the publication, use of, or reliance on this Safety and Health Fact Sheet. AWS also makes no guaranty or warranty as to the accuracy or completeness of any information published herein.