

## Finding the Code Number

There are normally three ways to identify a Lincoln welder:

- (1) Product Number – letter “K” or “U” followed by numbers and/or letters. For example; K2175-1.
- (2) Code Number – 4 to 5 digit number. For example; 10859.
- (3) Serial Number – 11 digit alphanumeric. For example; U1060512345.

When you register your product on myLincolnElectric.com, you need to enter the code number of the welder. A common mistake is to enter the product number.

The code number can be found on the nameplate of the welder, located either on the front or back of the unit.

